
City of Baltimore Wet Smoke and Dyed	Page 1 of 1	
Sewershed: Gwynns Falls	Company: Savin	Date: 7/21/2009
Test to be performed: Smoke Dyed Water X	Ground Condition: Dry ✓ Damp ☐ Wet ☐	Supervisor: JAW
Manhole_ID: S02CC1001MH	Test ID: <u>D1032-027031</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Manhole	S02CC1026MH
0			Water Level	
81.80000305	02		Tap Factory Active	From 3604 Woodbine
82.19999695			Dye Test Visible	@ TFA - toilet
82.19999695			Dye Test Visible	@ TFA - downspout
82.19999695			Manhole	S02CC1001MH
82.19999695			End of Survey	DYE TEST COMPLETED